



SERVICE BULLETIN

SB00001

Page 1 of 1

Cub Crafters, Inc. Considers Compliance Mandatory

EFFECTIVE DATE: This SERVICE BULLETIN is effective December 19, 2006

SUBJECT: STALL WARNING HORN

MODELS AFFECTED: CC11-100 S/N CC11-00001 thru CC11-00006.

COMPLIANCE TIME: Prior to Next Flight

PURPOSE: STALL WARNING LIP INSTALLATION

PARTS LIST:

| PART DESCRIPTION | QUANTITY |
|----------------------------------|-----------------|
| SC74301-001 (LIP, STALL WARNING) | 1 |
| TAPE (DOUBLE SIDED) | 1 |

INSTRUCTIONS:

STALL WARNING LIP INSTALLATION

Procedure:

1. CLEAN STALL WARNING SWITCH TANG AND SP74301-001 LIP WITH ISOPROPYL ALCOHOL OR LAQUER THINNER. (DRAWING SC74300 REF)
2. INSTALL STALL WARNING LIP IN ACCORDANCE WITH DRAWING SC74300 WITH TAPE SUPPLIED
3. ADJUST SWITCH POSITION IN ACCORDANCE WITH DRAWING SC74300.
4. MAKE COMPLIANCE ENTRY INTO AIRCRAFT LOGBOOK