



SERVICE BULLETIN

SB0014 Rev NC

Page 1 of 1

Cub Crafters, Inc. Considers Compliance Mandatory January 24, 2013

The parts of this Service Bulletin that change the Type Design of the aircraft have been approved by the FAA.

- EFFECTIVE DATE:** This SERVICE BULLETIN is effective **January 24, 2013.**
- SUBJECT:** SEAT BELT INSTALLATION
- MODELS AFFECTED:** CC18-180 SERIAL NUMBERS 0056 TO 0059
- COMPLIANCE TIME:** WITHIN NEXT 50 HOURS OR AT ANNUAL, WHICHEVER COMES FIRST.
- PURPOSE:** Cub Crafters has determined that on certain aircraft, the lap belts that were installed, while conforming to TSO-C114, do not match type approved data.

PARTS LIST:

<u>PART</u>	<u>DESCRIPTION</u>	<u>QTY</u>
VP2402-003	Fwd Seat, Right Hand Lap Belt	1
VP2402-004	Fwd Seat, Left Hand Lap Belt	1
VP2403-003	Aft Seat, Right Hand Lap Belt	1
VP2403-004	Aft Seat, Left Hand Lap Belt	1

INSTRUCTIONS:

1. Install VP2402-003, VP2402-004, VP2403-003, and VP2403-004 (right and left hand lap belts) in exact manner as the previously installed lap belts.
2. Make appropriate entry in aircraft log books.

If you are no longer in possession of this aircraft, please forward this information to the present owner/operator and notify Cub Crafters, Inc. of the address of the current owner to:

Cub Crafters, Inc.
1918 South 16th Avenue
Yakima, WA 98903-1212
1-877-484-7865 or 1-509-248-9491
support@cubcrafters.com

Please include the aircraft registration number, serial number, current name, and address of the owner and/or operator.