

## PROPELLER LOGBOOK

Registration Number: N849W

CCX-2000-0028

PROPELLER MODEL: HC-C2YR-1NW/NG8301W

PROPELLER S/N: NS3765B

LOGBOOK #\_/

This Propeller was installed new on serial number CCX-2000-0028  M. W. J-26-18  A&P Technician (Date)  Reg. Number: N849W CCX-2000  Dynamically Balanced Propeller ACES Systems.  Weight: 7.6 Angle: 40 IPS: 4	
A&P Technician (Date)  Reg. Number: N849W CCX-2000  Dynamically Balanced Propeller ACES Systems.  Weight: 7.6 Angle: 270 IPS:	
Reg. Number: N849W  CCX-2000  Dynamically Balanced Propeller ACES Systems.  Weight: 7.6  Angle: 270  IPS:	
Dynamically Balanced Propeller ACES Systems.  Weight: 7.6 Angle: 240 IPS:	
Weight: 7.6 Weight: 20.3  Angle: 270  IPS:	
Signed:	
Signed:	( ) (
Serviced Propeller serial number NS3765B with grease after test flight.  Tach Time: hrs	05
Serviced Propeller serial number NS3765B with grease after test flight.  Tach Time: 1-5 hrs.  O8/06/18	18
with grease after test flight.  Tach Time: 1-5 hrs.  08/06/18	
with grease after test flight.  Tach Time: 1-5 hrs.  08/06/18	
On m 08/06/18	
On m 08/06/18	
Signature (Date)	
Carson Aviation Services 2640 E. College Pkwy, Carson city, NV 89706 PH.775-841-0400	
PROPELLER  DATE: 5-Jun-2019 REG: N849W MAKE: MODEL: SN:	
TACH: 107.7 PTT: HOBBS: PTSMOH:  Performed Annual Inspection in accordance with Carson Aviation Services 100 hr/ Annual inspection checklist using CCX-2000 manual  Ground run engine and check for proper operation.	
I certify that this Propeller has been inspected in accordance with an annual inspection and was determined to be in an airworthy con	s a guide.
Troy Creeks A&P 3674511 IA	

ate	Prop TSN	TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
-				
				Carbon Cub
				N849W
				Date: 06/06/2019 Tach : 113.5
				The propeller was dynamically balanced using an ACES 2020HR system.
				Vibration of .26 I.P.S. was reduced to .02 I.P.S. at 2250 RPM by adding 19.5
				grams of weight to the spinner back plate split at 255 degrees from the index
				point.
				Good Vibes Dynamic Propeller Balancing
				Carson City, NV Kaymon Vasch P1539130
				Raymond Pasch P1539130
				A SECTION OF THE CONTRACTOR OF THE SECTION OF THE S
	CUBCRA	LETEDS		Cll Ave. Volcima WA 98903 (KYKM) Phone: (509) 248-1025 Fax: (509) 853-2783
-	CUBCRA	Services		Ave- Takilla, WA 70705 (ITTIM), Tilone (CT)
-	03/19/20		Hants	HC-C2YR-1NW SN NS3765B TT: 224.0
			* . 1 A	al inspection in accordance with Cub Crafters, Aircraft Maintenance Manual, Appendix A. shell # 6 grease. Inspected propeller for damage or defects. No discrepancies noted. I certify that
	this prop	eller has b	been inspected	d in accordance with the manufacturer's maintenance and inspection procedure on 03/19/2020, and or safe flight.
	U		a condition is	of safe right.
-	Todd Hil	debrand A	A&P 3089718	TIA (
_	May 3, 20	021		
	Hartzell	HC-C2YR	X2000-0028 -1NW/NG830	VectorAir Sys Airport Drive Sy
			TSN: 406.4	Aircraft Inspection & Repair Ene, Colorado 80516
	Minual inc	enaction c	of blades hub	inspection of propeller in accordance with FAR 43 appendix D and a checklist as a guide.  and spinner o.k. I certify this propeller has been inspected in accordance with the scope and
	detail of	14 CFR pa	art 43, append	dix D on this date and found to be in a condition for safe operationEND-
$\dashv$				Terrill Shafer
				AP2860279IA
1				
	Libel	A O		The state of the s

Date	N849W S/N:	CCX2000-0028		the state of the same	or to teach to a		50
Luid	Hartzell HC-C	2YR-1NW/NG830 Prop TSN: 507.0	1W S/N NS3765	Bruments, C	Vector Air Aircraft Inspection & Repair	Erie Municipal Airport 395 Airport Drive	and the same of th
	Performed an	annual condition i	inspection of prope	lles le second		Erie, Colorado 80516	The Ac
	Visual inspection	on of blades, hub	and spinner o.k. I	certify this prope	ce with FAR 43 appender Her has been inspected	dix D and a checklist as a guin accordance with the scope	iide.
	detail of 14 CF	R part 43, appendi	x D on this date an	d found to be in a	ler has been inspected condition for safe oper	ationEND	and
					(	12	
-+	•					Terrill Shafer	
	1					AP2860279IA	
	July 13 2023	CCX2000-0028			-7		
	Hartzell HC-C2	YR-1NW/NG8301	W S/N NS3765	B	VoctorAir	Ene Municipal Airport	
	- Tach: 600.8 F	Prop TSN: 600.8			VectorAir Aircraft Inspection & Repair	395 Airport Drive	
	Performed an a	annual condition i	nspection of prope	eller in accordan	ce with EAR 42 annua	ndix D and a checklist as a	
	Visual inspectio	n of blades, hub a	and spinner o.k. I	certify this prope	ller has been inspected	ndix D and a checklist as a good in accordance with the scop	guide.
+	detail of 14 C/ /	c part 43, appendi	X D on this date an	d found to be in	ller has been inspected a condition for safe ope	rationEND	
						1	7 -
+						Terrill Shafer	
						AP2860279IA	the state of the s
-							
			3				
Mac					•		
Document of the second	THE STATE OF THE S		Prope	eller	*	February	2.2024
William Control Man		REG# Hartze	ll	SN: PTSN	PTT TACH He	February	2,2024
Wife and the second	m e m e m e m e m e m e m e m e m e m e	REG# Hartze					2,2024
racks, n I	one found. Lubricat certify that I have in	N849W HC-C2N een inspected IAW Co red prop hub with ac inspected this <b>Prope</b>	II /R-1NW/NG8301W Cubcrafters/Hartzell a eroshell #6 grease. N Iler IAW the manufac	SN: PTSN NS3765B 635.i and FAR 43.13 Appe o Applicable AD's o ctures inspection gu	PTT TACH Home and the second of the second o	pubbs 71.0  Iltion Inspection. Checked spinner spection and was determined to be	and bulkhead
racks, n I	one found. Lubricat certify that I have in	N849W HC-C2N een inspected IAW Co red prop hub with ac inspected this <b>Prope</b>	II /R-1NW/NG8301W Cubcrafters/Hartzell a eroshell #6 grease. N Iler IAW the manufac	SN: PTSN NS3765B 635.i and FAR 43.13 Appe o Applicable AD's o ctures inspection gu	PTT TACH Home and the second of the second o	obbs 71.0 lition Inspection. Checked spinner	and bulkhead
racks, n I afe fligh	one found. Lubricat certify that I have in t. All work was acco	N849W HC-C2N een inspected IAW Code prop hub with aconspected this <b>Prope</b> complished in accordance.	II /R-1NW/NG8301W Cubcrafters/Hartzell a croshell #6 grease. N Iler IAW the manufac ance with the curren	SN: PTSN NS3765B 635.i and FAR 43.13 Appe o Applicable AD's o ctures inspection gu	PTT TACH Home and the second of the second o	pubbs 71.0  Iltion Inspection. Checked spinner spection and was determined to be	and bulkhead
racks, n I afe fligh	one found. Lubricat certify that I have in t. All work was acco	N849W HC-C2N een inspected IAW Code prop hub with aconspected this <b>Prope</b> complished in accordance.	II /R-1NW/NG8301W Cubcrafters/Hartzell a eroshell #6 grease. N Iler IAW the manufac	SN: PTSN NS3765B 635.i and FAR 43.13 Appe o Applicable AD's o ctures inspection gu	PTT TACH Home and the second of the second o	pubbs 71.0  Iltion Inspection. Checked spinner spection and was determined to be	and bulkhead
racks, n I afe fligh	one found. Lubricat certify that I have in	N849W HC-C2N een inspected IAW Code prop hub with aconspected this <b>Prope</b> complished in accordance.	II /R-1NW/NG8301W Cubcrafters/Hartzell a croshell #6 grease. N Iler IAW the manufac ance with the curren	SN: PTSN NS3765B 635.i and FAR 43.13 Appe o Applicable AD's o ctures inspection gu	PTT TACH Home and the second of the second o	pubbs 71.0  Iltion Inspection. Checked spinner spection and was determined to be	and bulkhead
racks, n I afe fligh	one found. Lubricat certify that I have in t. All work was acco	N849W HC-C2N een inspected IAW Code prop hub with aconspected this <b>Prope</b> complished in accordance.	II /R-1NW/NG8301W Cubcrafters/Hartzell a croshell #6 grease. N Iler IAW the manufac ance with the curren	SN: PTSN NS3765B 635.i and FAR 43.13 Appe o Applicable AD's o ctures inspection gu	PTT TACH Home and the second of the second o	pubbs 71.0  Iltion Inspection. Checked spinner spection and was determined to be	and bulkhead
racks, n I afe fligh	one found. Lubricat certify that I have in t. All work was acco	N849W HC-C2N een inspected IAW Code prop hub with aconspected this <b>Prope</b> complished in accordance.	II /R-1NW/NG8301W Cubcrafters/Hartzell a croshell #6 grease. N Iler IAW the manufac ance with the curren	SN: PTSN NS3765B 635.i and FAR 43.13 Appe o Applicable AD's o ctures inspection gu	PTT TACH Home and the second of the second o	pubbs 71.0  Iltion Inspection. Checked spinner spection and was determined to be	and bulkhead
racks, n I afe fligh	one found. Lubricat certify that I have in t. All work was acco	N849W HC-C2N een inspected IAW Code prop hub with aconspected this <b>Prope</b> complished in accordance.	II /R-1NW/NG8301W Cubcrafters/Hartzell a croshell #6 grease. N Iler IAW the manufac ance with the curren	SN: PTSN NS3765B 635.i and FAR 43.13 Appe o Applicable AD's o ctures inspection gu	PTT TACH Home and the second of the second o	pubbs 71.0  Iltion Inspection. Checked spinner spection and was determined to be	and bulkhead
racks, n I afe fligh	one found. Lubricat certify that I have in t. All work was acco	N849W HC-C2N een inspected IAW Code prop hub with aconspected this <b>Prope</b> complished in accordance.	II /R-1NW/NG8301W Cubcrafters/Hartzell a croshell #6 grease. N Iler IAW the manufac ance with the curren	SN: PTSN NS3765B 635.i and FAR 43.13 Appe o Applicable AD's o ctures inspection gu	PTT TACH Home and the second of the second o	pubbs 71.0  Iltion Inspection. Checked spinner spection and was determined to be	and bulkhead
racks, n I afe fligh	one found. Lubricat certify that I have in t. All work was acco	N849W HC-C2N een inspected IAW Code prop hub with acode proper with a code proper with a	II /R-1NW/NG8301W Cubcrafters/Hartzell a croshell #6 grease. N Iler IAW the manufac ance with the curren	SN: PTSN NS3765B 635.i and FAR 43.13 Appe o Applicable AD's o ctures inspection gu	PTT TACH Home and the second of the second o	pubbs 71.0  Iltion Inspection. Checked spinner spection and was determined to be	and bulkhead
racks, n I afe fligh	one found. Lubricat certify that I have in t. All work was acco	N849W HC-C2N een inspected IAW Code prop hub with acode proper with a code proper with a	II /R-1NW/NG8301W Cubcrafters/Hartzell a croshell #6 grease. N Iler IAW the manufac ance with the curren	SN: PTSN NS3765B 635.i and FAR 43.13 Appe o Applicable AD's o ctures inspection gu	PTT TACH Home and the second of the second o	pubbs 71.0  Iltion Inspection. Checked spinner spection and was determined to be	and bulkhead
racks, n I afe fligh	one found. Lubricat certify that I have in t. All work was acco	N849W HC-C2N een inspected IAW Code prop hub with acode proper with a code proper with a	II /R-1NW/NG8301W Cubcrafters/Hartzell a croshell #6 grease. N Iler IAW the manufac ance with the curren	SN: PTSN NS3765B 635.i and FAR 43.13 Appe o Applicable AD's o ctures inspection gu	PTT TACH Home and the second of the second o	pubbs 71.0  Iltion Inspection. Checked spinner spection and was determined to be	and bulkhead
racks, n I afe fligh	one found. Lubricat certify that I have in t. All work was acco	N849W HC-C2N een inspected IAW Code prop hub with acode proper with a code proper with a	II /R-1NW/NG8301W Cubcrafters/Hartzell a croshell #6 grease. N Iler IAW the manufac ance with the curren	SN: PTSN NS3765B 635.i and FAR 43.13 Appe o Applicable AD's o ctures inspection gu	PTT TACH Home and the second of the second o	pubbs 71.0  Iltion Inspection. Checked spinner spection and was determined to be	and bulkhead
racks, n I afe fligh	one found. Lubricat certify that I have in t. All work was acco	N849W HC-C2N een inspected IAW Code prop hub with acode proper with a code proper with a	II /R-1NW/NG8301W Cubcrafters/Hartzell a croshell #6 grease. N Iler IAW the manufac ance with the curren	SN: PTSN NS3765B 635.i and FAR 43.13 Appe o Applicable AD's o ctures inspection gu	PTT TACH Home and the second of the second o	pubbs 71.0  Iltion Inspection. Checked spinner spection and was determined to be	and bulkhead
racks, n I afe fligh	one found. Lubricat certify that I have in t. All work was acco	N849W HC-C2N een inspected IAW Code prop hub with acode proper with a code proper with a	II /R-1NW/NG8301W Cubcrafters/Hartzell a croshell #6 grease. N Iler IAW the manufac ance with the curren	SN: PTSN NS3765B 635.i and FAR 43.13 Appe o Applicable AD's o ctures inspection gu	PTT TACH Home and the second of the second o	pubbs 71.0  Iltion Inspection. Checked spinner spection and was determined to be	and bulkhead
racks, n I afe fligh	one found. Lubricat certify that I have in t. All work was acco	N849W HC-C2N een inspected IAW Code prop hub with acode proper with a code proper with a	II /R-1NW/NG8301W Cubcrafters/Hartzell a croshell #6 grease. N Iler IAW the manufac ance with the curren	SN: PTSN NS3765B 635.i and FAR 43.13 Appe o Applicable AD's o ctures inspection gu	PTT TACH Home and the state of	pubbs 71.0  Iltion Inspection. Checked spinner spection and was determined to be	and bulkhead
racks, n I afe fligh	one found. Lubricat certify that I have in t. All work was acco	N849W HC-C2N een inspected IAW Code prop hub with acode proper with a code proper with a	II /R-1NW/NG8301W Cubcrafters/Hartzell a croshell #6 grease. N Iler IAW the manufac ance with the curren	SN: PTSN NS3765B 635.i and FAR 43.13 Appe o Applicable AD's o ctures inspection gu	PTT TACH Home and the state of	pubbs 71.0  Iltion Inspection. Checked spinner spection and was determined to be	and bulkhead