


### Cub Crafters, Inc. Considers Compliance Mandatory

<b>EFFECTIVE DATE:</b>	This NOTIFICATION is effective April 20, 2007
<b>SUBJECT:</b>	Additional Cable Rub Strip.
<b>MODELS AFFECTED:</b>	CC11-100 S/N CC11-00024
<b>COMPLIANCE TIME:</b>	During annual inspections.
<b>PURPOSE:</b>	Additional inspection of cable rub strip required.
<b>INSTRUCTIONS:</b>	<ol style="list-style-type: none"><li>1. Inspect cable rub strip for excessive wear.</li><li>2. Ensure two loops of safety wire are on each arm of the rub strip.</li><li>3. Ensure cable rub strip is secure to fuselage.</li><li>4. Inspect overall condition of rub strip.</li><li>5. Contact Cub Crafters, Inc. for any discrepancies.</li></ol>



Additional cable rub strip

**Picture looking up and aft thru belly inspection cover**