

Cub Crafters, Inc. Considers Compliance Mandatory

EFFECTIVE DATE: This SERVICE BULLETIN is effective June 25, 2008

SUBJECT: Oil Line Additional Support

MODELS AFFECTED: CC11-100 S/N CC11-00001 THRU CC11-00076.

COMPLIANCE TIME: At the Next Maintenance Action

CONTINUED INSPECTION: Inspect at Condition Inspection

PURPOSE: To Add Additional Support for Oil Pressure Gauge Line

INSTRUCTIONS:

1. Remove cowling.
2. Using anti-chafe wrap and cable ties, secure the fire sleeved oil line to the oil filler neck (use the nearby attachment of the spark plug wires as a guide). Ensure the line is in a relaxed and unstressed condition on either side of the attachment to the oil filler neck. Refer to Figure 1.
3. Make a note in the aircraft logbook that Service Bulletin SB0011 has been complied with.



Figure 1 - Securing of the Oil Line to the Oil Filler Neck



SERVICE BULLETIN

SB00009

Page 2 of 2

Cub Crafters, Inc. Considers Compliance Mandatory

If you are no longer in possession of this aircraft, please forward this information to the present owner/operator and notify Cub Crafters, Inc. of the address of the current owner to:

Cub Crafters, Inc.
1918 S. 16th Avenue
Yakima, WA 98903.
1-877-484-7865 or 1-509-248-9491
support@cubcrafters.com

Please include the aircraft registration number, serial number, current name, and address of the owner and/or operator.