

**HARTZELL PROPELLER INC.**  
One Propeller Place  
Piqua, Ohio 45356-2634 U.S.A.  
Telephone: 937.778.4200  
Telex: 4332032  
Fax: 937.778.4391



**HARTZELL**

# PROPELLER LOGBOOK


PROPELLER MODEL HC-C2YR-1N

PROPELLER S/N NS 2820 B

LOGBOOK # 2

Date	Propeller TSN TSO	A/C Hrs	Description of all operations pertaining to Airworthiness Directives, Service Documents, Overhaul, Major or Minor Repair, and Inspections.
			<p><b>HARTZELL SERVICE CENTER</b> One Propeller Place Piqua, Ohio 45356 U.S.A</p> 
			<p><b>January 25, 2018</b> <b>S/N: NS2820B TSN 83.2 TSO N/A</b> Disassembled, clean, and inspected. Repaired propeller, reassembled, lubricated, static balanced, and inspected propeller. All work was performed in accordance with Hartzell manuals 113B-R43, 135F-R30, 159-R61, and 202A (Vol. 1-R56, Vol. 7-R45, Vol. 11-R36). For serial numbers and times reference attached Form # 25. See the airworthiness limitations section of Hartzell Owners' manual 115N for airworthiness limits information. Pertinent details of the work performed are on file at this agency under Work Order 13259 -----END-----</p>  <p>Corian Walker. Repairman # 3752710 Repair Station # SJ3R843L</p>

<p>PROP MODEL: HC-C2YR-1N PROP S/N: N52820B REG. NO: N508XC WORK ORDER: 5722-01-2018</p> <p><b>Prop Entries</b></p> <p>(3) Removed propeller from engine, sent to Hartzell for repair of cracked conductive sealant at blade roots, reinstalled and saftied. Reinstalled spinner.</p> <p>I certify that this PROPELLER has been inspected in accordance with an ANNUAL inspection per FAR 43 App. D and was determined to be in airworthy condition.</p> <p>DATE: 1/31/2018</p>	<p><b>Magnum Aviation</b> 13025 Murphy Ave. San Martin, CA 95046 Phone: 408-683-4102</p>	<p>DATE: 1/31/2018 A/C TSN: 83.2 PROP TT: 83.2 TACH: 83.2</p>
	<p>SIGNED:  Steve Lamb, Jr., IA: 3013346 For Magnum Aviation Inc.</p>	<p>Work Order: 5722-01-2018 Printed by EBis 3 (datcomedia.com)</p>

<p><b>COASTAL VALLEY</b> <i>Aviation Inc.</i> (805)928-7701 • www.cvamx.com</p> <p>Hartzell HCC2YR-1N SN NS2820B Tach: 124.0</p> <p>I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.</p>  <p>Richard Holder A&amp;P 3840719 IA</p>	<p>PROPELLER DATE: 6/12/2019 N508XC</p>
---	---



**Propeller**

October 9, 2019

es,  
ctions.

REG#	Hartzell	SN:	PTSN	PTT	TACH
N508XC	HCC2YR-1N	NS2820B	142.4	142.4	142.4

This **Propeller** has been inspected IAW Cubcrafters CC11-180 TC10000AMM Dated 12/29/2014 for an **Annual** Inspection. Checked spinner and bulk head for cracks, none found. Checked torque on all prop bolts all satisfactory. No Applicable AD's or SB's as of 10/09/2019

I certify that I have inspected this **Propeller** IAW an **Annual** inspection and was determined to be in airworthiness condition. All work was accomplished in accordance with the current Federal Aviation Regulation and manufacture maintenance instruction. Aircraft is returned to service at this tach time only.

Signed  Date 10-9-2019  
Jeffrey Willems AP.3291817.IA





**Sonoma**  
JET CENTER

**Sonoma Jet Center**  
6000 Flightline Dr.  
Santa Rosa, Ca. 95403

Date: 10/02/2020; Aircraft: N508XC; Type: CC19-180; S/N: CC19-0005; Tach: 218.10; Total Time: 218.10; Prop - Type: HC-C2YR-1N/NG8301-5, S/N: N52820B, Time: 218.10

Performed a Propeller Annual Inspection per Cubcrafters Inspection form and FAR43 appendix D. Removed spinner, inspected spinner for defects, none found. Inspected prop hub for leaks and defects none found. Installed spinner.

I certify that this Propeller has been inspected in accordance with an ANNUAL inspection and was determined to be in an airworthy condition.

  
Corey Wheeler IA 563064190


Date



**Sonoma**  
JET CENTER

**Sonoma Jet Center**


6000 Flightline Dr.  
Santa Rosa, Ca. 95403

3.

Date: 10/12/2021; Aircraft: N508XC; Type: CC19-180; S/N: CC19-0005; Tach: 326.90; Total Time: 326.90; Prop - Type: HC-C2YR-1N/NG8301-5, S/N: N52820B, Time: 326.90

Performed a Propeller Annual Inspection per CubCrafters Inspection form and FAR43 appendix D. Removed spinner insp backing plate, greased prop with Aeroshell #6, installed spinner.

I certify that this Propeller has been inspected in accordance with an ANNUAL inspection and was determined to be in an airworthy condition.

  
Corey Wheeler IA 563064190



**COASTAL VALLEY**  
*Aviation Inc.*

(805)928-7701 • [www.cvamx.com](http://www.cvamx.com)

Hartzell HCC2YR-1N SN NS2820B


PROPELLER


DATE: 6/12/2019

N508XC

Tach: 124.0

I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.

  
Richard Holder A&P 3346719 IA

Burrows Aviation llc 


1008 N Cedar Rd ~ Deer Park, WA 99006 ~ (509) 276-5312

11-02-2023 Tach and TT : 405.0

Annual inspection completed this date per FAR 43 Appendix D checklist.  
AD's checked through 2023-22 , DRS, FAA Website. Lubed propeller hub  
with Aeroshell #6 grease. Propeller is airworthy.

Burrows Aviation LLC by it's President Matt L Burrows

A&P 3165624IA



\*\*\*\*\* END \*\*\*\*\*